


Evaluation Wheel Excavator		<a href="http://www.mevas.net">www.mevas.net</a>	
Customer/Location:	<a href="#">Prima/Hardenberg</a>	vers 02-22	
Date:	<a href="#">10.08.2023</a>		
Machine / type:	<a href="#">Hyundai HW140</a>	Hour reading:	<a href="#">9520</a>
Serial No.:	<a href="#">0140</a>	Year:	<a href="#">2017</a>
Inspector:	<a href="#">Chris</a>	stick length:	<a href="#">2,55m</a>
CE <input checked="" type="checkbox"/> EPA <input checked="" type="checkbox"/>	A/C <input checked="" type="checkbox"/> stick check valve <input checked="" type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	quick coupler <input checked="" type="checkbox"/> DPF <input checked="" type="checkbox"/>
mono-boom <input type="checkbox"/>	boom variable <input checked="" type="checkbox"/>	hammer lines <input checked="" type="checkbox"/>	lines for grapple / shear <input checked="" type="checkbox"/>
<b>cab</b>		cab door	<a href="#">good</a>
seat, arm rests	<a href="#">good</a>	windows & mirrors	<a href="#">good</a>
switches, levers	<a href="#">sticky joysticks</a>	wipers, washer	<a href="#">good</a>
gauges & warn lights	<a href="#">good</a>	floor mat & pedals	<a href="#">small cut in floor mat</a>
aircon / heater	<a href="#">good</a>	cab structure	<a href="#">good</a>
<b>engine</b>		Serial No.	<a href="#">22230417</a>
leaks & seals	<a href="#">no leaks seen</a>	cooling system	<a href="#">good</a>
oil condition & level	<a href="#">good</a>	blow by	<a href="#">normal</a>
exhaust, muffler	<a href="#">good</a>	belts & filters	<a href="#">good</a>
smoke	<a href="#">normal</a>	coolant condition	<a href="#">good</a>
<b>visual inspection exterior</b>		counterweight	<a href="#">good</a>
chassis & carbody	<a href="#">good</a>	bumpers & covers	<a href="#">good</a>
side doors	<a href="#">good</a>	outriggers & blade	<a href="#">good</a>
stairs, hand rails	<a href="#">good</a>	lights, batteries	<a href="#">good</a>
boom	<a href="#">good</a>	paintwork	<a href="#">good</a>
stick	<a href="#">good</a>	rims, wheel nuts	<a href="#">good</a>
<b>hydraulics &amp; drive train</b>		boom cylinders	<a href="#">good</a>
hoses & lines	<a href="#">good</a>	stick cylinder	<a href="#">good</a>
pump & valve bloc	<a href="#">good</a>	bucket cylinder	<a href="#">good</a>
transmission gear	<a href="#">good</a>	outr/blade cylinders	<a href="#">good</a>
axles	<a href="#">good</a>	universal joints	<a href="#">good</a>
swivel joint	<a href="#">good</a>		
<b>functional test</b>		suspension lock	<a href="#">good</a>
pins boom	<a href="#">moderate play</a>	pump noises	<a href="#">normal</a>
pins stick	<a href="#">moderate play</a>	slew ring play	<a href="#">moderate</a>
pins bucket	<a href="#">moderate play</a>	brake & park brake	<a href="#">good</a>
boom self drift	<a href="#">none</a>	electric system	<a href="#">good</a>
swing drive/brake	<a href="#">good</a>	drive operation	<a href="#">good</a>
<b>tools</b>	<a href="#">Eurosteel</a>	additional bucket	<a href="#">N/A</a>
bucket dimension	<a href="#">1,8m</a>	coupler brand	<a href="#">Verachtert Rototilt</a>
bucket condition	<a href="#">good</a>	coupler condition	<a href="#">good</a>
<b>tires</b>	<b>mm (%) remaining life</b>	size:	<a href="#">600/50R22.5</a>
front right	<a href="#">10%</a>	twin / mono:	<a href="#">mono</a>
front left	<a href="#">10%</a>	spacer rings:	<input type="checkbox"/>
rear right	<a href="#">20%</a>	damages or cuts:	<a href="#">no</a>
rear left	<a href="#">20%</a>	solid:	<input type="checkbox"/>
<b>problems, details:</b>			
<a href="#">pressurized cab, EPA-label 2016</a>			
<a href="#">The excavator is in good condition. No major problems found. New set of tires recommended.</a>			
dimensions for transport L x W x H in meter:	<a href="#">8,2 x 2,5 x 3,07</a>		