


Evaluation Tracked Excavator		<a href="http://www.mevas.eu">www.mevas.eu</a>	
Customer/location:	<i>Prima</i>	vers 11/16	
Date:	<i>07.03.2019</i>		
Machine / type:	<i>330CL</i>	Hour reading:	<i>14.928 (1)</i>
Serial No.:	<i>CAP02179</i>	Year:	<i>2006</i>
Inspector:	<i>Chris</i>	stick length:	<i>3.1m</i>
CE label <input checked="" type="checkbox"/>	EPA label <input type="checkbox"/>	boom check valve <input checked="" type="checkbox"/>	DPF <input type="checkbox"/>
auto lube <input type="checkbox"/>	stick check valve <input checked="" type="checkbox"/>	boom variable <input type="checkbox"/>	DEF (add blue) <input type="checkbox"/>
blade <input type="checkbox"/>	auxiliary lines <input type="checkbox"/>	quick coupler type:	
<b>cab</b>		cab door	<i>retainer to be adjusted</i>
seat		windows & mirrors	<i>(2)</i>
switches	<i>rev switch missing</i>	wipers	<i>blades worn</i>
gauges & warn lights	<i>good</i>	floor mats	<i>good</i>
aircon / heater	<i>low performance / good</i>	cab structure	<i>good</i>
<b>engine</b>		Serial No.	
leaks & seals	<i>no leaks seen</i>	cooling system	<i>good</i>
oil condition & level	<i>good</i>	blow by	<i>moderate</i>
exhaust, muffler	<i>good</i>	belts & filters	<i>good</i>
smoke	<i>normal</i>	coolant condition	<i>good</i>
<b>visual inspection exterior</b>		covers	<i>good</i>
chassis, track frame	<i>bent slightly, box attached</i>	side doors	<i>good</i>
engine hood	<i>good</i>	compartments	<i>good</i>
steps, hand rails	<i>U/C steps missing</i>	bumpers / catwalk	<i>slight dents in RHS rear</i>
boom	<i>plated</i>	lights	<i>roof lights missing</i>
stick	<i>plated</i>	paintwork	<i>faded and chipped</i>
<b>hydraulics</b>		boom cylinders	<i>seepages</i>
hoses,lines,swivel	<i>good</i>	stick cylinder	<i>leaking</i>
pump and valve bloc	<i>good</i>	bucket cylinder	<i>scratched chrome rod</i>
<b>functional test</b>		boom self drift	<i>not seen</i>
pins boom	<i>moderate play</i>	pump noises	<i>normal</i>
pins stick	<i>moderate play</i>	slew ring play	<i>normal</i>
pins bucket	<i>N/A</i>	electrics	<i>good</i>
swing drive/brake	<i>good</i>	drive train	<i>good</i>
<b>tools</b>		bucket 2, size, type	<i>N/A</i>
bucket 1, size & type	<i>digging, 1.5m3</i>	condition	
condition	<i>new</i>	coupler condition	<i>N/A</i>
<b>U/C</b>	<b>remaining life %</b>	track pitch	
bushings	<i>100%</i>	track links	<i>50%</i>
shoes	<i>100%</i>	sprockets	<i>80%</i>
idlers	<i>40%</i>	rollers	<i>10%</i>
carrier rollers	<i>50%</i>	shoe width in mm:	<i>600mm</i>
<b>problems, details</b>	<i>(1) The hour meter is not working - shows constant hours</i>		
	<i>(2) The windscreen and one mirror are cracked. One mirror is missing</i>		
	<i>The refill pump is not working.</i>		
	<i>The machine is in general good condition. Boom and stick are welded, the hour meter is not working - machine ECM has logged 22.000h.</i>		
dimensions for transport L x W x H in meter:			