


Evaluation Mobile Material Handler		www.mevas.net	
Customer/Location:	Prima/Hardenberg	vers 02-22	
Date:	20.08.2024		
Machine / type:	Fuchs MHL350	Hour reading:	11.470
Serial No.:	3502101201	Year:	2006
Inspector:	Chris	stick length:	6,0m
CE <input checked="" type="checkbox"/> EPA <input type="checkbox"/>	A/C <input checked="" type="checkbox"/> generator <input type="checkbox"/>	industrial boom <input type="checkbox"/>	industrial stick <input type="checkbox"/>
stabilizer blade <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/> stabilizers <input checked="" type="checkbox"/>	auxiliary lines <input checked="" type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>
cab		cab door	good
seat, arm rests	burn holes in seat	windows, mirrors	good
switches, levers	worn joysticks	wipers, washer	good
gauges, warn lights	good	floor mat, covers	good
aircon / heater	good	cab structure	good
engine		Serial No.	
leaks & seals	no leaks seen	cooling system	good - air cooled
oil condition & level	good	blow by	normal
exhaust, muffler	good	belts & filters	good
smoke	normal	coolant condition	
visual inspection exterior		sheet metal	good
chassis	good	bumpers	good
engine hood	gas strut weak	outriggers/blade	good
stairs, hand rails	gas strut weak	lights, batteries	good
boom	slight dents	paintwork	good
stick	slight dents	rims, wheel nuts	good
hydraulics & drive train		boom cylinders	good
hoses & lines	good	stick cylinder	good
pump and valve bloc	good	bucket cylinder	good
transmission gear	good	outr/blade cylinders	good
swivel joint	good	universal joints	good
functional test		swing drive & brake	good
pins boom	moderate play	pump noises	normal
pins stick	moderate play	slew ring play	no tool attached
generator, cab raiser	not attached	brakes	good
pins bucket & linkage	not attached	drive operation	good
tools	no tool attached	rotation test	--
grapple size, kind	--	hoses/connectors	--
arm condition	--	pins & bushings	--
tires	mm (%) remaining life	size:	12.00-20
front right	50% due cuts + damages	twin / mono:	twin
front left	50% due cuts + damages	spacer rings:	<input checked="" type="checkbox"/>
rear right	50% due cuts + damages	cuts:	yes
rear left	50% due cuts + damages	solid:	<input checked="" type="checkbox"/>
problems, details:			
RHS arm rest safety not working.			
The machine is in good condition. No major problems detected.			
dimensions for transport L x W x H in meter:		11,5m x 2,8m x 3,0m	