


Evaluation Wheel Loader		<a href="http://www.mevas.eu">www.mevas.eu</a>	
Customer:	<i>Prima Equipment</i>	vers 06/18	
Date:	<i>9-6-2020</i>		
Machine / type:	<i>Komatsu WA 380-6</i>	location:	<i>Hardenberg</i>
Serial No.:	<i>H60797</i>	Hour reading:	<i>15368</i>
Inspector:	<i>Hans</i>	Year:	<i>2009</i>
CE <input checked="" type="checkbox"/> A/C <input checked="" type="checkbox"/>	EPA <input checked="" type="checkbox"/> Auto-Greaser <input checked="" type="checkbox"/>	Hydrostat <input type="checkbox"/>	quick coupler <input checked="" type="checkbox"/>
3rd valve <input checked="" type="checkbox"/>	supplemental steering <input checked="" type="checkbox"/>	weigh load <input checked="" type="checkbox"/>	Parts book <input type="checkbox"/> Op-Manual <input type="checkbox"/>
<b>cab</b>		cab door	<i>rust penetration</i>
seat, arm rests	<i>burnhole, taped arm rests</i>	windows & mirrors	<i>Window lock broken RHS</i>
switches, levers	<i>Good</i>	wipers, washer	<i>Good</i>
gauges & lamps	<i>Good</i>	floor mat	<i>Good</i>
aircon / heater	<i>low performance</i>	cab structure	<i>Good</i>
<b>engine</b>		Serial No.	<i>6754DOHH10</i>
leaks & seals	<i>Good</i>	cooling system	<i>fan guard bent, coolers clogged with dirt</i>
oil condition & level	<i>Good</i>	blow by	<i>Normal</i>
exhaust, muffler	<i>Good</i>	belts & filters	<i>change required</i>
smoke	<i>Normal</i>	coolant condition	<i>Level low</i>
<b>exterior</b>		counterweight	<i>Scratched</i>
chassis & lift arm	<i>good</i>	fenders	<i>some dents, parts missing on bonnet</i>
engine hood	<i>repaired, cooler grill cracked</i>	lights, batteries	<i>Good</i>
stairs, hand rails	<i>Steps rear missing, bent slightly</i>	paintwork	<i>scratched and rusty</i>
<b>power train</b>		rims, wheel nuts	<i>Good</i>
axles/differentials	<i>Good</i>	universal joints	<i>Good</i>
gearbox	<i>Small seepage</i>	transfer gear	<i>Good</i>
power train	<i>Good</i>	transm. noises	<i>Normal</i>
<b>hydraulics</b>		steering cylinders	<i>Good</i>
hoses & lines	<i>Good</i>	pumps & valves	<i>Good</i>
lift & tilt cylinders	<i>Tilt cylinder weld repaired</i>	steering orbital	<i>Good</i>
<b>functional test</b>		full bucket lift in seconds:	<i>6,1</i>
steering	<i>Moderate play</i>	articulation play	<i>no bucket attached</i>
transmission test	<i>Good</i>	loader pins	<i>Moderate play</i>
stall test	<i>2100 RPM / Double 1990</i>	electric system	<i>weightload disconnected</i>
brake / park brake	<i>Good</i>	supplem. steering	<i>To be checked</i>
<b>bucket</b>		width / capacity	<i>--</i>
edges / teeth	<i>--</i>	side condition	<i>--</i>
bottom		quick coupler	<i>ES Syst 2000 few bends on top</i>
<b>tires</b>	mm or % good	size, brand	comments, damages
front right	<i>New</i>	<i>MTP 23,5 X 25</i>	
front left	<i>New</i>		
rear right	<i>New</i>		
rear left	<i>New</i>		
<b>problems, details:</b>			
<i>The machine is in general good condition according to the age and hour level. Some smaller repairs and service required.</i>			
transport dimensions L x W x H in meter:		<i>L 7,15 X W 2,75 X H 3,50 m</i>	