Evaluation Wheel Ex		<u>www.mevas.eu</u>	(R)
Customer/Location:	Prima Equipment	vers 06/18	
Date:	08.05.2019		
Machine / type:	Robex 140W 9A	Hour reading:	9055
Serial No.:	0003	Year:	2014
Inspector:	WB	stick length:	2,55
CE 🗸 EPA 🗌	A/C ☑ stick check valve ☑	boom check valve <a> 	
quick coupler:	boom 2-piece □	auxiliary lines ☑	boom VA □ DPF □
cab		cab door	good
seat, arm rests	cushion dirty, rest good	windows & mirrors	1)
switches, levers	good	wipers, washer	good
gauges & warn lights		floor mat & pedals	good
aircon / heater	AC not cooling	cab structure	good
engine		Serial No.	
leaks & seals	good	cooling system	good
oil condition & level	new, good	blow by	normal
exhaust, muffler	good	belts & filters	good
smoke	good	coolant condition	good
visual inspection ex		counterweight	good
chassis & carbody	good	bumpers & covers	good
side doors		outriggers & blade	good
stairs, hand rails	good	lights, batteries	good
boom	good	paintwork	just some rusty spots
stick	good	rims, wheel nuts	good
hydraulics		boom cylinders	good
hoses & lines	good	stick cylinder	good
pump & valve bloc	good	bucket cylinder	good
swivel joint	good	-	good
functional test	 	suspension lock	good
pins boom	good	pump noises	good
pins stick	good	slew ring play	good
pins bucket	good	brake & park brake	good
boom self drift	none	electric system	good
swing drive/brake	good	drive operation	good
tools		bucket 2 (width)	g
bucket 1 (width cm)	standard 1,20m	bucket 2 condition	
bucket 1 condition	new, good	quick coupler cond.	
tires	% remaining life	size:	10.00-20
front right	60	twin / mono:	twin
front left	60	spacer rings:	
rear right	60	damages or cuts:	
rear left	60	solid:	
problems, details		Soilu.	
או טטופוווס, עכנמווס			
1) lower front window is cracked, windscreen has traces from wiper			
1) lower none window is cracked, windscreen has traces north wiper			
2) covers in eah partially lose, one air vent missing			
2) covers in cab partially lose, one air vent missing			
Marking in its many larger little or No. 11 and Incomplete to a larger to the			
Machine is in good condition. No major problems detected.			
dimensions for transport L x W x H in meter:			