

Cat Electronic Technician 2015A v1.0

Product Status Report

Product Status Report

Parameter	Value
Product ID	LKJ00541
Equipment ID	CAT D6T
Comments	www.mevas.eu

Cat Monitor System D6

Parameter	Value
ECM Part Number	2524501-01
Software Group Part Number	3231271-00
Software Group Release Date	DEC07
Mon Sys Harness Code	44

Logged Diagnostic Codes [Diagnostic Clock = 10842,3226 hours] - Cat Monitor System D6

Code	Description	Occ.	First	Last
248- 2	Invalid Cat Data Link data	10	10838	10841

Logged Event Codes [Diagnostic Clock = 10842,3226 hours] - Cat Monitor System D6

Code	Description	Occ.	First	Last
No Logged Events				

Active Diagnostic Codes - Cat Monitor System D6

Code	Description
No Active Codes	

Active Event Codes - Cat Monitor System D6

Code	Description
No Active Events	

Current Totals - Cat Monitor System D6

Description	Value	Unit
Total Operating Hours	10842	hours
Total Distance	Unavailable	km
Total Forward Distance	Unavailable	km
Total Reverse Distance	Unavailable	km

Configuration - Cat Monitor System D6

Description	Value	Unit
Information Units Status	Metric	

Powertrain D6 (LKJ00541)

Parameter	Value
Product ID	LKJ00541
Equipment ID	
ECM Part Number	3045687-02
ECM Serial Number	03216073MS
Software Group Part Number	3676879-00
Software Group Release Date	13SEP10
Active Diagnostic Codes Present	No
Harness Code	46

Logged Diagnostic Codes [Diagnostic Clock = 10842,3670 hours] - Powertrain D6 (LKJ00541)

Code	Description	Occ.	First	Last
2674- 2	Multi-Velocity Program Enable Switch : Erratic, Intermittent, or Incorrect	7	10775	10842
585- 2	Transmission Output Speed Sensor #1 : Erratic, Intermittent, or Incorrect	1	10840	10840
673- 2	Transmission Output Speed Sensor #2 : Erratic, Intermittent, or Incorrect	1	10840	10840
1079- 3	Blade Control Handle Tilt Position Sensor : Voltage Above Normal	5	10835	10835
168- 4	Electrical System Voltage : Voltage Below Normal	2	10835	10835
468- 3	Service Brake Pedal Position Sensor : Voltage Above Normal	1	10835	10835
468- 4	Service Brake Pedal Position Sensor : Voltage Below Normal	2	10835	10835
618- 2	Left Secondary Brake Switch : Erratic, Intermittent, or Incorrect	1	10835	10835
1078- 3	Blade Control Handle Lift Position Sensor : Voltage Above Normal	4	10835	10835

Logged Event Codes [Diagnostic Clock = 10842,3670 hours] - Powertrain D6 (LKJ00541)

Code	Description	Occ.	First	Last
No Logged Events				

Active Diagnostic Codes - Powertrain D6 (LKJ00541)

Code	Description
No Active Codes	

Active Event Codes - Powertrain D6 (LKJ00541)

Code	Description
No Active Events	

Current Totals - Powertrain D6 (LKJ00541)

Description	Value	Unit
Total Distance	36020,70	km
Total Forward Distance	19670,40	km
Total Reverse Distance	16037,70	km
Total Hours Coasting In Neutral	161	hours
Total Neutral Gear Operating Hours	2992	hours
Total First Forward Gear Operating Hours	430	hours
Total Second Forward Gear Operating Hours	4257	hours
Total Third Forward Gear Operating Hours	45	hours
Total First Reverse Gear Operating Hours	194	hours
Total Second Reverse Gear Operating Hours	2626	hours
Total Third Reverse Gear Operating Hours	35	hours
Total Powertrain Oil Filter Bypass Hours	0,05	hours
Total Distance Coasting In Neutral	312,6	km

Configuration - Powertrain D6 (LKJ00541)

Description	Value	Unit
Product ID	LKJ00541	
Equipment ID		
Application Number	241	
Transmission Maximum Forward Gear	3	
Transmission Maximum Reverse Gear	3	
Blade Installation Status	Single Tilt	
Transmission Calibration Selected Clutch	0	
AccuGrade System Installation Status	Not Installed	
AccuGrade Temporary Installation Status	Not Installed	
AccuGrade Temporary Installation Time Remaining	3000	min
Advanced Machine Security System Installation Status	Installed	
Sunday Security System Bypass Start Time	00:00	
Sunday Security System Bypass Stop Time	00:00	
Monday Security System Bypass Start Time	00:00	
Monday Security System Bypass Stop Time	00:00	
Tuesday Security System Bypass Start Time	00:00	
Tuesday Security System Bypass Stop Time	00:00	

Wednesday Security System Bypass Start Time	00:00	
Wednesday Security System Bypass Stop Time	00:00	
Thursday Security System Bypass Start Time	00:00	
Thursday Security System Bypass Stop Time	00:00	
Friday Security System Bypass Start Time	00:00	
Friday Security System Bypass Stop Time	00:00	
Saturday Security System Bypass Start Time	00:00	
Saturday Security System Bypass Stop Time	00:00	
Total Tattletale	0	
Xmsn Serial Number		

Shift Count Matrix - Powertrain D6 (LKJ00541)

To	N	R1	R2	R3	1	2	3
From							
N	---	6668	78630	1104	8773	76634	1867
R1	4442	---	13364	13	48235	536	2
R2	76801	1775	---	8536	5207	651067	128
R3	1910	16	5227	---	9	906	4059
1	4123	54523	6515	5	---	15611	34
2	91712	323	639235	141	15018	---	3654
3	2012	3	302	2323	61	5055	---

Product Link (LKJ00541)

Parameter	Value
Machine Serial Number	LKJ00541
Dealer Identification Code	L240
DBS Machine Make Code	AA
ECM Serial Number	3400B766LQ
Wireless Transmission Device Serial Number	DQCAT0068447
Software Group Part Number	3846463-00
Software Group Release Date	AUG2011
Software Group Description	PL-300 3.1.3 PROD

Logged Diagnostic Codes [Diagnostic Clock = 10842,3226 hours] - Product Link (LKJ00541)

Code	Description	Occ.	First	Last
1250- 9	Remote Communication Module : Abnormal Update Rate	4	10835	10838

Logged Event Codes [Diagnostic Clock = 10842,3226 hours] - Product Link (LKJ00541)

Code	Description	Occ.	First	Last
No Logged Events				

Active Diagnostic Codes - Product Link (LKJ00541)

Code	Description
------	-------------

No Active Codes	
-----------------	--

Active Event Codes - Product Link (LKJ00541)

Code	Description
No Active Events	

Configuration - Product Link (LKJ00541)

Description	Value	Unit
Maintenance Mode	Off	
Machine Serial Number	LKJ00541	
DBS Machine Make Code	AA	
Dealer Identification Code	L240	
Registration E-Mail Address Username	STSPL	
Registration E-Mail Address Domain	ZEPPELIN.COM	
Event/Diagnostic Report Interval (SMU)	20	hours
Event/Diagnostic Message Interval (RT)	168	hours
Report Start Time	2012-07-31 23:00	
Warning Level 3 Report Configuration	Report Immediately	
Warning Level 2 Report Configuration	Report Immediately	
Warning Level 1 Report Configuration	Report Immediately	
Diagnostic Report Configuration	Report Immediately	
Operating Hours Report Configuration	On	
Number of Daily Machine Location Messages Configuration	4	
Position Report Minimum Location Change	0	meters
Fuel Consumed Report Configuration	On	
Global Gram Enable Status	Disabled	
GPS Fix Validity Time Duration	60,0	min
Preferred Wireless Service Configuration	Satellite Premium #2	
Digital Sensor Input #1 Type Configuration	Not Configured	
Digital Input #1 Monitoring Condition	All Conditions	
Digital Sensor Input #1 Description	DIGITAL INPUT 1	
Digital Sensor Input #1 Delay Time	30,0	sec
Digital Sensor Input #2 Type Configuration	Not Configured	
Digital Input #2 Monitoring Condition	All Conditions	
Digital Sensor Input #2 Description	DIGITAL INPUT 2	
Digital Sensor Input #2 Delay Time	30,0	sec
Digital Sensor Input #3 Type Configuration	Not Configured	
Digital Input #3 Monitoring Condition	All Conditions	
Digital Sensor Input #3 Description	DIGITAL INPUT 3	
Digital Sensor Input #3 Delay Time	30,0	sec
Digital Sensor Input #4 Type Configuration	Not Configured	
Digital Input #4 Monitoring Condition	All Conditions	
Digital Sensor Input #4 Description	DIGITAL INPUT 4	
Digital Sensor Input #4 Delay Time	30,0	sec
Embedded Communication Adapter Installation Status	Not Installed	

C9 D6T (THX28179)

Parameter	Value
Equipment ID	LKJ00541
Engine Serial Number	THX28179
ECM Serial Number	20206140JL
Personality Module Part Number	3111900-00
Personality Module Release Date	MAR07
Personality Module Description	TTT-D6T

Logged Diagnostic Codes [Diagnostic Clock = 10842,3226 hours] - C9 D6T (THX28179)

Code	Description	Occ.	First	Last
91- 2	Throttle Position Sensor : Erratic, Intermittent, or Incorrect	1	10838	10838
1639- 2	Machine Security System Module : Erratic, Intermittent, or Incorrect	1	10838	10838
1639- 9	Machine Security System Module : Abnormal Update Rate	1	10838	10838
42- 5	Injector Actuation Valve : Current Below Normal	2	10835	10835

Logged Event Codes [Diagnostic Clock = 10842,3226 hours] - C9 D6T (THX28179)

Code	Description	Occ.	First	Last
E198 (1)	Low Fuel Pressure	1	10835	10835

Active Diagnostic Codes - C9 D6T (THX28179)

Code	Description
No Active Codes	

Active Event Codes - C9 D6T (THX28179)

Code	Description
No Active Events	

Current Totals - C9 D6T (THX28179)

Description	Value	Unit
Total Operating Hours	10842	hours
Total Idle Time	3151:24	hours
Total Fuel	262107	L
Total Idle Fuel	12348	L
Total Max Fuel	471332	L
Engine Starts	11236	
Lifetime Total Engine Revolutions	962906568	rev

Configuration - C9 D6T (THX28179)

Description	Value	Unit
Equipment ID	LKJ00541	
Engine Serial Number	THX28179	
ECM Serial Number	20206140JL	

Personality Module Part Number	3111900-00	
Personality Module Description	TTT-D6T	
Variable Pitch Engine Fan	Disabled	
Variable Pitch Engine Fan Blade Cooling Position	Unavailable	
Engine Fan Purge Cycle Interval	Unavailable	sec
Engine Fan Purge Cycle Duration	Unavailable	sec
Engine Fan Suspend Purge	Unavailable	
Engine Fan Manual Purge	Unavailable	
Engine Fan Temperature Dependent Radiator Purge	Unavailable	
Engine Fan Control	On	
Top Engine Fan Speed	Unavailable	rpm
Ether Solenoid Configuration	Continuous Flow Solenoid	
FLS	-20	
FTS	54	
Engine Security System Status	Enabled	
Total Tattletale	5	
Prelube Enb	Off	