Evaluation Tracked E	Excavator	www.mevas.eu	R
Customer/location:	Prima Equipment	vers 06/18	
Date:	424		MANA
Machine / type:	EC300	Hour reading:	7184
Serial No.:	211056	Year:	2011
Inspector:	WB	stick length:	3.05m
CE label ☑	EPA label □	boom check valve	
auto lube 🔽	stick check valve ☑	boom variable	DEF (add blue)
blade □	auxiliary lines 🗹	quick coupler type:	Verachtert CW55H
cab		cab door	good
seat	good	windows & mirrors	good
switches	good	wipers	good
gauges & warn lights	good	floor mats	good
aircon / heater	good	cab structure	good
engine	9000	Serial No.	9000
leaks & seals	no leaks seen	cooling system	good
oil condition & level		blow by	minor
exhaust, muffler	good good	belts & filters	
smoke	normal	coolant condition	good
			good
visual inspection ext		covers	good
chassis, track frame	good	side doors	good
engine hood	good	compartments	good
steps, hand rails	good	bumpers / catwalk	good
boom	good	lights	good
stick	good	paintwork	good
hydraulics		boom cylinders	good
hoses,lines,swivel	good	stick cylinder	good
pump and valve bloc	good	bucket cylinder	good
functional test		boom self drift	none
pins boom	moderate play in base pin	pump noises	normal
pins stick	moderate play	slew ring play	good
pins bucket	moderate play	electrics	good
swing drive/brake	good	drive train	just one speed (Slow)
tools		bucket 2, size, type	
bucket 1, size & type	1.5m	condition	
condition	70%	coupler condition	
U/C	remaining life %	track pitch	
bushings	50	track links	70
shoes	70	sprockets	100
idlers	70	rollers	70
carrier rollers	70	shoe width in mm:	900
problems, details		0.100 111011111111111111111111111111111	
problemo, detane			
The machine is in good condition. No major problems detected.			
The machine is in good condition. No major problems detected.			
dimensions for transpo	ort L x W x H in meter:	10.5m x 3.49m x 3.1	7m (bucket attached)