| Evaluation Articulated | Water Truck | www.mevas.net | (B) |
|---|-------------------------------|---------------------------------|-------------------------------|
| Customer/location: | Prima Equipment Hardenberg | vers 02-23 | |
| Inspector: | Bernd | | |
| Machine/type: | CAT 740 Water Truck | Hour reading: | 2186 |
| Serial No.: | B1P05187 | Year: | 2010 |
| CE ☑ AC ☑ | EPA ☐ auto lube ☐ | DPF 🗌 | extended side walls |
| tailgate 🗌 | heated bed secondary steering | OP-Manual | Parts book |
| cab | | cab door | Good |
| seat | Good | windows, mirrors | Good |
| switches, levers | Good | wipers, washer | Good |
| gauges, warn lights | Good | floor mat | Good |
| aircon / heater | Good | cab structure | Good |
| engine | | Serial No. | LHX24477 |
| leaks & seals | Good | cooling system | Good |
| oil condition / level | recently changed | blow by | minor |
| exhaust, muffler | Good | belts & filters | Good |
| smoke | normal | coolant condition | Good |
| exterior | Oned | cooler grills | Good |
| chassis & frames | Good | bumpers & fenders | Good |
| engine hood | Good | lights | Good recently repainted |
| stairs, hand rails | Good | paintwork | good, recently repainted Good |
| power train | Cood | rims, wheel nuts | |
| axles & differentials transmission | Good | universal joints brake disks | Good Good |
| hydraulics | Good | steering cylinders | Good |
| hoses & lines | Good | pumps & valves | Good |
| lift cylinders | No | steering orbital | Good |
| functional test | INO | steering | Good |
| stall speed 1st gear | | articulation play | Good |
| transmission fwd. | Good | body lift | No |
| transmission rev. | Good | electrics, batteries | Good |
| retarder | Good | diff lock | Good |
| brakes holding 1/min | 0000 | park brake | Good |
| water tank | | pins | Good |
| welding condition | Good | pumps & valves | Good |
| tank | Good | side wall condition | Good |
| tires | mm (%) remaining | brand/type | general condition, remould |
| front right | 90% | Michelin | , |
| front left | 90% | Michelin | |
| center right | 80% | Michelin | |
| center left | 80% | Michelin | |
| rear right | 80% | Michelin | |
| rear left | 80% | Michelin | |
| tire size: | 29,5 R 25 | | |
| problems, details: | | | |
| MEGA MAC8EU water tank fitted with 30k liters capacity. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| The truck is in good condition. No problems found. Ready to work. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| dimonologo on increases | NI v M v II in mater | | |
| dimensions as inspected | ALAWATIII MELET. | | |