Evaluation Tracked Excavator		www.mevas.eu	
Customer/location:	*Hardenberg*	vers 06/18	
Date:	*19.12.2018*		
Machine / type:	*Hyundai HX145LCR*	Hour reading:	*491*
Serial No.:	*000177*	Year:	*2016*
Inspector:	*B.Hecker*	stick length:	*3,00 Meter*
CE label ☑	EPA label ☐	boom check valve ☑	DPF ☑
auto lube ☐	stick check valve ☑	boom variable ☐	DEF (add blue) ☑
blade ☐	auxiliary lines ☑	quick coupler type:	*Geith Hydraulisch*
cab		cab door	*Good*
seat	*Good*	windows & mirrors	*Good*
switches	*some blind covers missing*	wipers	*Good*
gauges & warn lights	*Good*	floor mats	*Good*
aircon / heater	*Good*	cab structure	*Good*
engine		Serial No.	*no plate found*
leaks & seals	*Good*	cooling system	*Good*
oil condition & level	*Good*	blow by	*Good*
exhaust, muffler	*Good*	belts & filters	*Good*
smoke	*Good*	coolant condition	*Good*
visual inspection exterior		covers	*Good*
chassis, track frame	*Good*	side doors	*good*
engine hood	*Good*	compartments	*Good*
steps, hand rails	*Good*	bumpers / catwalk	*Good*
boom	*Good*	lights	*small scratches*
stick	*Good*	paintwork	*Good*
hydraulics		boom cylinders	*Good*
hoses,lines,swivel	*Good*	stick cylinder	*Good*
pump and valve bloc	*Good*	bucket cylinder	*Good*
functional test		boom self drift	*Good*
pins boom	*Good*	pump noises	*Good*
pins stick	*Good*	slew ring play	*Good*
pins bucket	*Good*	electrics	*batteries empty*
swing drive/brake	*Good*	drive train	*Good*
tools		bucket 2, size, type	*No*
bucket 1, size & type	*GP*	condition	*No*
condition	*unused*	coupler condition	*some scratches on chrome rod*
U/C	**remaining life %**	track pitch	*512 mm*
bushings	*100 %*	track links	*100 %*
shoes	*100 %*	sprockets	*100 %*
idlers	*100 %*	rollers	*100 %*
carrier rollers	*100 %*	shoe width in mm:	*700 mm*
problems, details			
equipped with a refill pump			
The machine is in general good condition. No major problems found.			
dimensions for transport L x W x H in meter:			