Evaluation Tracked Excavator		www.mevas.eu	
Customer/location:	*Prima Equipment*	vers 06/18	
Date:	*06.12.2018*		
Machine / type:	*CAT 319 DL*	Hour reading:	*10426*
Serial No.:	*ZGZ00484*	Year:	*2011*
Inspector:	*WB*	stick length:	*2,65*
CE label ☑	EPA label ☐	boom check valve ☑	DPF ☐
auto lube ☐	stick check valve ☐	boom variable ☐	DEF (add blue) ☐
blade ☐	auxiliary lines ☑	quick coupler type:	*Verachtert CW30 Hyd*
cab		cab door	*good*
seat	*good*	windows & mirrors	*crack in front window*
switches	*good*	wipers	*good*
gauges & warn lights	*good*	floor mats	*good*
aircon / heater	*good*	cab structure	*good*
engine		Serial No.	*good*
leaks & seals	*good*	cooling system	*good*
oil condition & level	*good / OK*	blow by	*normal*
exhaust, muffler	*good*	belts & filters	*good*
smoke	*normal*	coolant condition	*good*
visual inspection exterior		covers	*good*
chassis, track frame	*good*	side doors	*good*
engine hood	*good*	compartments	*good*
steps, hand rails	*good*	bumpers / catwalk	*good*
boom	*good*	lights	*good*
stick	*good*	paintwork	*good*
hydraulics	*swing drive oil too low*	boom cylinders	*good*
hoses,lines,swivel	*good*	stick cylinder	*good*
pump and valve bloc	*good*	bucket cylinder	*good*
functional test		boom self drift	*none*
pins boom	*moderate play*	pump noises	*normal*
pins stick	*minor play*	slew ring play	*good*
pins bucket	*minor play*	electrics	*good*
swing drive/brake	*good*	drive train	*good*
tools		bucket 2, size, type	
bucket 1, size & type		condition	
condition		coupler condition	*good*
U/C	**remaining life %**	track pitch	
bushings	*70%*	track links	*70%*
shoes	*70%*	sprockets	*70%*
idlers	*70 / 50%*	rollers	*70%*
carrier rollers	*70%*	shoe width in mm:	*700*
problems, details			
Machine is in good condition. No major repairs required.			
dimensions for transport L x W x H in meter:			