Evaluation Mobile Ma	aterial Handler	www.mevas.net	(R)
Customer/Location:	Prima/Hardenberg	vers 02-22	
Date:	07.03.2024		
Machine / type:	Fuchs MHL331	Hour reading:	10212
Serial No.:	4089	Year:	2016
Inspector:	Chris	stick length:	3,7m
CE ☑ EPA ☑	A/C ☑ generator □	industrial boom 🗸	industrial stick 🗸
stabilizer blade	auto lube 🗸 stabilizers 🗸	auxiliary lines 🔽	hyd. cab riser 🗸
cab		cab door	good
seat, arm rests	good	windows, mirrors	good
switches, levers	good	wipers, washer	good
gauges, warn lights	good	floor mat, covers	good
aircon / heater	good/good	cab structure	good
engine		Serial No.	11643599
leaks & seals	no leaks seen	cooling system	good
oil condition & level	good	blow by	normal
exhaust, muffler	good	belts & filters	good
smoke	normal	coolant condition	good
visual inspection ext		sheet metal	good
chassis	good	bumpers	good
engine hood	good	outriggers/blade	good
stairs, hand rails	good	lights, batteries	good
boom	good	paintwork	faded
stick	good	rims, wheel nuts	good
hydraulics & drive tra		boom cylinders	
hoses & lines		· · · · · · · · · · · · · · · · · · ·	good
	auxiliary sockets oily	stick cylinder	good
pump and valve bloc	good	bucket cylinder	good
transmission gear	good	outr/blade cylinders	good
swivel joint	good	universal joints	good
functional test		swing drive & brake	good
pins boom	minor play	pump noises	normal
pins stick	minor play	slew ring play	moderate (no tool attached)
	good/good	brakes	good
μ	N/A	drive operation	good
tools		rotation test	not tested
grapple size, kind	N/A	hoses/connectors	N/A
arm condition	N/A	pins & bushings	N/A
tires	mm (%) remaining life	size:	10.00-20
front right	20%	twin / mono:	twin
front left	20%	spacer rings:	✓
rear right	20%	cuts:	
rear left	20%	solid:	✓
problems, details:			
The machine is in good condition for hour level.			
dimensions for transpo	ort L x W x H in meter	10,1 x 2,5 x 3,3 (with	out beacon)
Laonenene	AL = A TT A I I III III III III III	. 5, 1 A 2, 5 A 5, 5 (WILLIA	© 2022 LMEVAS