


Evaluation Paver Asphalt		www.mevas.eu	
customer:		vers 12/17	
inspector:	<i>Adam</i>		
machine / type:	<i>DEMAG DF115C</i>		
Serial No.:	<i>90000015</i>	year:	<i>2005</i>
CE <input checked="" type="checkbox"/> EPA <input type="checkbox"/> Canopy <input type="checkbox"/>		hour reading:	<i>8547</i>
Screed Heating Electric <input type="checkbox"/>		Extension boxes <input checked="" type="checkbox"/>	Screed Heating Gas <input checked="" type="checkbox"/>
cab / canopy		Max. screed width:	<i>5 M</i>
seats	<i>Two seats</i>	floor boards, steps	<i>Good</i>
operator console	<i>Good</i>	work lights	<i>One not working</i>
gauges & warn lamps	<i>Good</i>	screed heat control	<i>appears ok</i>
canopy	<i>N/A</i>	paving contr. panels	<i>Good</i>
engine		grab irons	<i>Good</i>
leaks & seals	<i>No leaks</i>	Engine brand	<i>Deutz</i>
oil condition & level	<i>Good</i>	cooling system	<i>Good</i>
exhaust, muffler	<i>Good</i>	blow by	<i>Normal</i>
smoke	<i>Normal</i>	belts & filters	<i>Good</i>
visual inspection		coolant condition	<i>Below minimum</i>
chassis	<i>Good</i>	auger condition	<i>Good</i>
covers/doors	<i>Dent</i>	screed extensions	<i>Good</i>
paintwork	<i>Repainted partially</i>	hopper / bunker	<i>Good</i>
lights, bacons	<i>Good</i>	tamper condition	<i>Good</i>
truck push rollers	<i>Good</i>	conveyor & chain	<i>Good</i>
hydraulics		lateral guides	<i>-</i>
hose lines	<i>Good</i>	extension cylinders	<i>Good</i>
pumps & drive motors	<i>Good</i>	leveling cylinders	<i>Good</i>
functional test		vibrator (tamper)	<i>Good</i>
auger fwd & reverse	<i>Good</i>	tamper vibration	<i>Good</i>
conveyor speed contro	<i>N/A</i>	screed extension	<i>Good</i>
tractor speed control	<i>Good</i>	screed heating	<i>1)</i>
tractor steering	<i>Good</i>	height control	<i>Good</i>
drive train		slope control	<i>Good</i>
tires	RHS % remaining <i>N/A</i>	LHS % remaining	damages
rollers	<i>50%</i>	<i>50%</i>	
chains	<i>50%</i>	<i>50%</i>	
track pads	<i>30 mm</i>	<i>30 mm</i>	<i>Cuts</i>
tamper wear measurement, remaining mm			
RHS	<i>10mm</i>	RHS extension	<i>5,5mm</i>
LHS	<i>11mm</i>	LHS extension	<i>7,5mm</i>
problems, repairs, recommendation			
<i>The machine appears in good condition. Screed not tested as there is no gas available.</i>			
dimension for transport L x W x H in meter:		<i>7,5 x 3,0 x 2,6</i>	