Evaluation Tracked Excavator		www.mevas.eu	
Customer/location:	*Prima Hardenberg*	vers 02-20	
Date:	*13.11.2020*		
Machine / type:	*Hyundai Robex 380LC-9*	Hour reading:	*12 462*
Serial No.:	*B0000351*	Year:	*2012*
Inspector:	*B. Hecker*	stick length:	*3,25 Meter*
CE label ☑	boom check valve ☑	adjustable boom ☐	DPF ☐ DEF (AdBlue) ☐
auto lube ☑	stick check valve ☑	stabilizer blade ☐	A/C ☑
lines hammer ☑	lines grapple/shear ☑	quick coupler type:	*Verachtert CW45 hydraulic*
cab		cab door, covers	*Good*
seat, arm rests	*Good*	windows & mirrors	*Good*
switches, joysticks	*Good*	wipers, washer	*Good*
gauges & warn lights	*Good*	floor mat	*Good*
aircon / heater	*Good*	cab structure	*Good*
engine		Serial No.	*illegible plate*
leaks & seals	*Good*	cooling system	*Good*
oil condition & level	*Good*	blow by	*Good*
exhaust, muffler	*Good*	belts & filters	*Good*
smoke	*Good*	coolant condition	*Good*
visual inspection exterior		covers / sheets	*Good*
chassis, track frame	*Good*	side doors	*Good*
engine hood	*Good*	compartments	*Good*
steps, hand rails	*Good*	bumpers / catwalk	*Good*
boom	*Good*	lights, batteries	*Good*
stick	*Good*	paintwork	*Good*
hydraulics		boom cylinders	*Good*
hoses,lines,swivel	*Good*	stick cylinder	*Good*
pump and valve bloc	*Good*	bucket cylinder	*Good*
functional test		boom self drift	*Good*
pins boom	*Good*	pump noises	*Good*
pins stick	*Good*	slew ring play	*0,6mm play - good*
pins bucket	*Good*	electric system	*Good*
swing drive/brake	*Good*	drive train	*Good*
tools		bucket 2, size,type	*No*
bucket 1, size & type	*No*	condition	*No*
condition	*No*	coupler condition	*Good*
U/C	**remaining life %**	rollers	*70%*
bushings	*70 %*	track links	*70 %*
shoes	*70 %*	sprockets	*70 %*
idlers	*70 %*	track pitch in mm:	*650 mm*
carrier rollers	*70 %*	shoe width in mm:	*900 mm*
problems, details			
The machine is in general good condition. No major problems found.			
dimensions for transport L x W x H in meter:		*10,50 x 3,65 x 3,30*	