Evaluation Mini Excavator		www.mevas.net	®
Customer/Location: Date:	Prima/Hardenberg 21.03.2023	vers 02-22	
Machine / type:	Hyundai Robex18-9	Hour reading:	2402
Serial No.:	255	Year:	2019
Inspector:	Chris	stick length:	1,1m
CE  EPA	A/C hammer line	grapple hydr.	Parts book Op-Manual
adjustable U/C 🗹	open ROPS	Coupler brand:	
cab		cab door	good
seat, arm rests	good	windows, mirrors	good
switches, levers	good	wipers, washer	good
gauges, warn lights	good	floor mats	good
aircon / heater	good	cab structure	good
engine	9000	Serial No.	
leaks & seals	no leaks visible	cooling system	good
oil condition & level	good	blow by	normal
exhaust, muffler	good	belts & filters	good
smoke	normal	coolant condition	good
exterior	, normal	covers	slight dent LHS rear
chassis	good	compartments	good
engine door	good	blade	good
grab irons	good	bumpers	good
boom	good	lights, batteries	good
stick	good	paintwork	good
hydraulics	geod	boom cylinders	good
hoses & lines	good	stick cylinder	good
pump noise	normal	bucket cylinder	good
oil level/condition	good	valves/couplers	good
functional test	geou	swing drive / brake	good
pins boom	good	slew ring play	good
pins stick	good	side tilt boom	good
pins bucket / linkage	good	drive train	good
tools	good	bucket 2 width	
bucket 1 width	1,0mm DC bucket	condition	
condition		coupler condition	good
U/C	condition	ocapior corrainor:	condition
tracks in %	90%	rollers & guides	90%
track width	220mm rubber tracks	idlers & tensioner	90%
cuts, damages	none	sprockets	90%
problems, details:		op. concic	
The excavator is in good condition. No major problems detected.			
dimensions for transport L x W x H in meter: approx. 3,85 x 1,0 x 2,3			
dimensions for transport L x W x H in meter:			