Evaluation Tracked Excavator		www.mevas.eu	
Customer/location:	*Prima Equipment*	vers 06/18	
Date:	*06.12.2019*		
Machine / type:	*CAT 345 DL*	Hour reading:	*13130*
Serial No.:	*LKY00388*	Year:	*2011*
Inspector:	*WB*	stick length:	*3,00m*
CE label ☑	EPA label ☐	boom check valve ☑	DPF ☐
auto lube ☑	stick check valve ☑	boom variable ☐	DEF (add blue) ☐
blade ☐	auxiliary lines ☑	quick coupler type:	*hydraulic*
cab		cab door	*good*
seat	*good*	windows & mirrors	*good*
switches	*good*	wipers	*good*
gauges & warn lights	*good*	floor mats	*good*
aircon / heater	*good*	cab structure	*good*
engine		Serial No.	*good*
leaks & seals	*none / good*	cooling system	*good*
oil condition & level	*good*	blow by	*normal*
exhaust, muffler	*good*	belts & filters	*good*
smoke	*normal*	coolant condition	*good*
visual inspection exterior		covers	*good*
chassis, track frame	*good*	side doors	*good*
engine hood	*damaged, retainer missing*	compartments	*good*
steps, hand rails	*no steps on track frame*	bumpers / catwalk	*good*
boom	*good*	lights	*one damaged on RHS*
stick	*good*	paintwork	*good*
hydraulics		boom cylinders	*good*
hoses,lines,swivel	*good*	stick cylinder	*good*
pump and valve bloc	*good*	bucket cylinder	*good*
functional test	*good*	boom self drift	*none*
pins boom	*good*	pump noises	*normal*
pins stick	*good*	slew ring play	*moderate*
pins bucket	*good*	electrics	*good*
swing drive/brake	*good*	drive train	
tools		bucket 2, size, type	
bucket 1, size & type	*rock bucket 1.80m*	condition	
condition	*50%*	coupler condition	*good*
U/C	**remaining life %**	track pitch	
bushings	*100*	track links	*100*
shoes	*100*	sprockets	*50*
idlers	*100*	rollers	*40*
carrier rollers	*100*	shoe width in mm:	*600*
problems, details			
Machine is in good condition. No major problems detected.			
dimensions for transport L x W x H in meter:			