


Evaluation Mobile Material Handler		www.mevas.eu	
Customer/Location:	<i>Prima Equipment</i>	vers 06/18	
Date:	<i>9-6-2020</i>		
Machine / type:	<i>Fuchs MHL335</i>	Hour reading:	<i>12471</i>
Serial No.:	<i>335310/4051</i>	Year:	<i>2015</i>
Inspector:	<i>Hans</i>	stick length:	<i>3,97</i>
CE <input checked="" type="checkbox"/> EP <input checked="" type="checkbox"/>	A/C <input checked="" type="checkbox"/> generator <input type="checkbox"/>	industrial boom	<input checked="" type="checkbox"/> industrial stick <input checked="" type="checkbox"/>
stabilizer blade <input type="checkbox"/>	auto lube <input checked="" type="checkbox"/> stabilizers <input checked="" type="checkbox"/>	auxiliary lines <input checked="" type="checkbox"/>	hyd. cab riser <input checked="" type="checkbox"/>
cab		cab door	<i>Good</i>
seat, arm rests	<i>Good</i>	windows, mirrors	<i>Good</i>
switches, levers	<i>Good</i>	wipers, washer	<i>Good</i>
gauges, warn lights	<i>Good</i>	floor mats	<i>Good</i>
aircon / heater	<i>Good</i>	cab structure	<i>small dent in front RHS</i>
engine		Serial No.	<i>11643617</i>
leaks & seals	<i>Good</i>	cooling system	<i>Good</i>
oil condition & level	<i>Good</i>	blow by	<i>normal</i>
exhaust, muffler	<i>normal</i>	belts & filters	<i>Good</i>
smoke	<i>normal</i>	coolant condition	<i>Good</i>
visual inspection exterior		sheet metal	<i>Good</i>
chassis	<i>Good</i>	bumpers	<i>Good</i>
engine hood	<i>Good</i>	outriggers/blade	<i>Good</i>
stairs, hand rails	<i>Good</i>	lights, batteries	<i>Good</i>
boom	<i>dent</i>	paintwork	<i>some scratches</i>
stick	<i>Good</i>	rims, wheel nuts	<i>Good</i>
hydraulics		boom cylinders	<i>Good</i>
hoses & lines	<i>Good</i>	stick cylinder	<i>Good</i>
pump and valve bloc	<i>Good</i>	bucket cylinder	<i>Good</i>
swivel joint	<i>Good</i>	outr/blade cylinders	<i>Good</i>
functional test		swing drive & brake	<i>Good</i>
pins boom	<i>Good</i>	pump noises	<i>Normal</i>
pins stick	<i>Moderate play</i>	slew ring play	<i>0,7mm</i>
generator, cab raiser	<i>--/Good</i>	brakes	<i>Good</i>
pins bucket & linkage	<i>Moderate play</i>	drive train	<i>Good</i>
tools		rotation test	
grapple size, kind	<i>QC ES CW 3 Hydr. act.</i>	hoses/connectors	<i>Good</i>
arm condition		pins & bushings	
tires	% remaining life	size:	<i>10.00x20</i>
front right	<i>30%</i>	twin / mono:	<i>Twin</i>
front left	<i>30%</i>	spacer rings:	<input checked="" type="checkbox"/>
rear right	<i>30%</i>	cuts:	<i>Some</i>
rear left	<i>30%</i>	solid:	<input checked="" type="checkbox"/>
problems, details	<i>Machine in good working condition</i>		
dimensions for transport L x W x H in meter:		<i>L 9,90 X W 2,75 X H 3,30 m</i>	